Delaware State House (Old State House)
East side of the Green
Dover
Kent County
Delaware

HABS No. DE-199

HABS DEL. I-DOV,

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

FOLLOWS...

Historic American Buildings Survey National Park Service Department of the Interior Washington, D.C. 20240 United States Department of the Interior National Park Service Washington, D.C. 20240

HISTORIC AMERICAN BUILDINGS SURVEY

HABS DEL, 1-DOV,

January 1983

elaware	COUNTY		TOWN OR VI	CINITY
	Kent		Dover	
ISTORIC NAME OF STRUCTURE	(INCLUDE SOURCE	FOR NAME)		HABS NO.
elaware State House			•	DE-199
ECONDARY OR COMMON NAMES	OF STRUCTURE			·
Old State House				·
COMPLETE ADDRESS (DESCRIBE	E LOCATION FOR RUP	(AL SITES)		
East side of the Green				
DATE OF CONSTRUCTION (INC	LUDE SOURCE) AF	CHITECT(S) (IN	ICLUDE SOURCE)	
1787-1792				
SIGNIFICANCE (ARCHITECTURA State House built in 1787, foundations. Served as St from 1792 to 1873. Heavi	-92 using brick fr tate House from 17	com the previou '92 to 1932 and	ıs 1722 State	House for its
STYLE (IF APPROPRIATE) Georgian	, <u> </u>			
MATERIAL OF CONSTRUCTION ((INCLUDE STRUCTURA	L SYSTEMS)		
Brick bearing walls; Flemi	ish bond on front.	common bond o	on sides	
SHAPE AND DIMENSIONS OF ST				GES ARE ACCEPTABLE)
ectangular; two-and-a-hal	lf stories. one-st	orv wing on so	outh, annex to	east (rear)
EXTERIOR FEATURES OF NOTE Gable roof with balustrade center, broken pediment on topped water table.			-	
INTERIOR FEATURES OF NOTE Sweeping double stairway o	curves back and me	ets over doorw		restored to Original
INTERIOR FEATURES OF NOTE Sweeping double stairway o state house appearance, in	curves back and me acluding furnishin	ets over doorw		restored to Original
INTERIOR FEATURES OF NOTE Sweeping double stairway of state house appearance, in MAJOR ALTERATIONS AND ADDITECT 1873-75: Mansard roof; to	curves back and me acluding furnishin TIONS WITH DATES ower in center of	ets over doorw	way; interior	
INTERIOR FEATURES OF NOTE Sweeping double stairway of state house appearance, in MAJOR ALTERATIONS AND ADDITEM 1873-75: Mansard roof; to 1836-1926: Various addition 1910: Original roofline a	eurves back and me icluding furnishin TIONS WITH DATES ower in center of ons.	ets over doorw gs. front obscurir	ray; interior	indow. exterior and interic
INTERIOR FEATURES OF NOTE Sweeping double stairway of state house appearance, in MAJOR ALTERATIONS AND ADDITED 1873-75: Mansard roof; to 1836-1926: Various additi	eurves back and me icluding furnishin TIONS WITH DATES ower in center of ons.	ets over doorw gs. front obscurir	ray; interior	indow.
INTERIOR FEATURES OF NOTE Sweeping double stairway of state house appearance, in MAJOR ALTERATIONS AND ADDITEM 1873-75: Mansard roof; to 1836-1926: Various additional confine a	eurves back and me icluding furnishin TIONS WITH DATES ower in center of ons. and second-floor w	ets over doorw gs. front obscurir	ray; interior	indow. exterior and interic
INTERIOR FEATURES OF NOTE Sweeping double stairway of state house appearance, in MAJOR ALTERATIONS AND ADDI 1873-75: Mansard roof; to 1836-1926: Various additing 1910: Original roofline appresent CONDITION AND USE	eurves back and me icluding furnishin TIONS WITH DATES ower in center of ons. and second-floor w	ets over doorw gs. front obscurir	ray; interior	indow. exterior and interic
INTERIOR FEATURES OF NOTE Sweeping double stairway of state house appearance, in MAJOR ALTERATIONS AND ADDI 1873-75: Mansard roof; to 1836-1926: Various additinglo: Original roofline appresent CONDITION AND USE OTHER INFORMATION AS APPROSOURCES OF INFORMATION (IN	TIONS WITH DATES ower in center of ons. and second-floor w	ets over doorwas. front obscuring indows restore	ray; interior ng Palladian w ed; 1974-76:	indow. exterior and interic restoration
INTERIOR FEATURES OF NOTE Eweeping double stairway of state house appearance, in MAJOR ALTERATIONS AND ADDI 1873-75: Mansard roof; to 1836-1926: Various additing 1910: Original roofline appresent CONDITION AND USE	curves back and medicluding furnishing furnishing furnishing the follower in center of constant second-floor was constant for the follower in the follower was and for the follower in the follower was and for the follower in the follower i	ets over doorwes. front obscuring indows restore N NATIONAL REC	ray; interior ng Palladian w nd; 1974-76: GISTER, STATE	indow. exterior and interior restoration REGISTERS, ETC.)

Alison K. Hoagland, Historic American Buildings Survey

ADDENDUM TO:
DELAWARE STATE HOUSE
East Side of the Green
Dover
Kent County
Delaware

HABS No. DE-199
HABS
DEL,
1-DOV,

XEROGRAPHIC COPIES OF COLOR TRANSPARENCIES

HISTORIC AMERICAN BUILDINGS SURVEY
National Park Service
U.S. Department of the Interior
Washington, D.C., 20013